

Software product	Devices Supported as of January, 2009											
	DATA STAR®	100 Series	200 Series	CENTRON®	CENTRON (C12.19)	CENTRON (V&I)	VECTRON®	SENTINEL	FULCRUM® SL320	FULCRUM SQ400	QUANTUM®	QUANTUM Q1000
PC-PRO+® (16 BIT) 3.5 - 3.5.3	YES	YES	YES	YES	NO	NO	YES	NO	YES	YES	YES	NO
PC-PRO+® Advanced 9.50	NO	NO	YES(1)	YES	YES	YES	YES*	YES	YES(1)	YES(R)	YES(R)	YES
PC-PRO+® Views 9.50	NO	NO	YES(R)	YES(R)	YES(R)	YES(R)	YES(R)	YES(R)	YES(R)	YES(R)	YES(R)	YES(R)
Shop-Pro™ 9.50	NO	NO	YES	YES	YES	YES	YES	YES	YES	YES(R)	YES(R)	YES
HH-Pro™ 9.50	NO	NO	YES	YES	YES	YES	YES	YES	NO	NO	NO	NO
Field-Pro™ 9.50	NO	NO	YES	YES	YES	YES	YES	YES	NO	NO	NO	NO
EnergyAudit™ 4.30	NO	NO	NO	NO	NO	NO	YES(R)	YES(R)	YES(R)	YES(R)	YES(R)	YES(R)

* No PRO-READ or Factory exports available for VECTRON

(R): Read Only

(1): Initialize with imported programs

Software product	Software Qualified on Operating Systems as of January, 2009									
	DOS® 6.22	Windows® 3.1	Windows NT 3.51	Windows NT 4.0, SP 6.0+	Windows 95	Windows 98 SE	Windows Me	Windows 2000 Profesional	Windows XP Profesional	Windows Vista® Profesional
PC-PRO+® (16 BIT) 3.5 - 3.5.3	NO	NO	NO	YES**	YES	NO	NO	NO	NO	NO
PC-PRO+® Advanced 9.50	NO	NO	NO	NO	NO	NO	NO	NO	YES	YES
PC-PRO+® Views 9.50	NO	NO	NO	NO	NO	NO	NO	NO	YES	YES
Shop-Pro™ 9.50	NO	NO	NO	NO	NO	NO	NO	NO	YES	YES
HH-Pro™ 9.50	NO	NO	NO	NO	NO	NO	NO	NO	YES	YES
Field-Pro™ 9.50	NO	NO	NO	NO	NO	NO	NO	NO	YES	YES
EnergyAudit™ 4.30	NO	NO	NO	YES	NO	NO	NO	YES	YES	NO

**PC-PRO+ 3.5 - 3.5.3 will not function properly if MS04-012 (KB828741), Microsoft® security patch is installed.

Meter	Latest Firmware Revisions
QUANTUMQ1000	5.01M
SENTINEL	5.xx